

s.s."ANDREAS K"

The Boiler Survey became due 4,31.

The donkey boiler was partly examined at Plymouth in December 1930 and the Surveyors recommended the record of DBS 12,30 when some repairs were effected and the safety valves adjusted. These repairs were recommended to be completed before the end of 6,31.

The Istanbul Surveyor now reports that the machinery has been examined on account of grounding and recommends the main engines, auxiliary machinery and boilers be removed to enable the necessary repairs to be carried out on vessel's arrival at a home port, as the machinery is considered to be out of use in its present condition.

The case is submitted for the consideration of the Committee.

Wm

23.6.31.

ARR 91



© 2021

Lloyd's Register
Foundation

W582-0347