

...ed by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME SS 'Soengei Gerong'

Rpt. Sourabaya No. 2829

remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/32).

...re of Survey ~~COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No.~~

This Survey, due 8-31 ~~partly~~ ^{now} held at ~~at~~ ^{now}

~~completed~~, and the following repairs carried out (due to damage):-

The Surveyor reports that owing to the propeller striking a submerged object, minor repairs have now been effected

It is submitted the vessel is eligible to remain as classed, with notation of BS 12-31 as recommended.

Subject to the DONKEY BOILER not being used again.

Cwf
11-1-32



© 2021

Lloyd's Register Foundation

W587-0138