

GLASGOW REPORT No 50529

Rpt. 14.

Port of Glasgow

14th. May 1930

REPORT ON MASTS, SPARS, AND RIGGING.

Sirs,

Having, in accordance with your instructions, examined the Masts, Spars, Iron Work of same, and Rigging, of the

(Name of Vessel) S/S "Mickleton"

on the (Date of examination) Thirteenth day of May 1930,

I have to report that I found Fore Stay Screw requires

renewing. Port and Star. Fore stays and Screws should be

renewed. Service on remainder of rigging requires reserving

where broken.

remainder was found in good condition.

All rigging Screws require overhauling.

2 Derrick Preventers should be renewed.

All the renewals and repairs referred to above have been satisfactorily carried out. R. Farley

Wm. H. Farley

Fee £ - : 10 : 0

To the Surveyors,

Lloyd's Register of Shipping,

342 Argyle St. C.2

2m, 6, 29.



© 2021

Lloyd's Register
Foundation

W59-0161