

on account of Damage (the cause of which... and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided, on this form. State also the dates and initials of any letters respecting this case. 4. 28-11-31

m. 11.30.

POSTPONED SURVEYS.

Case of the Steel S.S. "RIPLEY CASTLE"
 No. 82618 in Reg. Bk. 7446/4636 tons, Built 1917-6 ms
 Classed +100 A1 Owners Union Castle Mail S.S. Co Ltd
12.30 Port of Registry London
3.5.29 L.M.C. M.S. 5.29 B.S. 3.30 O.G. R 7.28
(S) N. 12.30
 Survey Due Boiler Survey due 3,31.

The London Surveyors state they have been informed by the Owners' Representative that this vessel is laid up at Southampton and that, in the meantime, nothing is being done in connection with the above survey.

Submitted action be deferred. DA 27/4/31


Committee's Minute:

TUE. 28 APR 1931

JE. 10 NOV 1931

Decision

Deferred | *Deferred*
MM | *MM*



© 2021

Lloyd's Register
 Foundation

(per Sec. 29)

Selling Expenses (if chargeable)£

Received by me.

8.12.1931

T. H. Myden

Surveyor to Lloyd's

(if assigned and now ve
 m?
 to
 broke
 wood
 ms:
 Copper, or Y
 (State i
 When pu
 Boats
 Masts, Yard
 Condition, h
 (State i
 Sails
 Equipment
 Anchors, No
 Tables (Sta
 „ length
 „ Rule
 Hawser &
 Standing a
 in the l
 main as
 m
 cov