

1m.9.25.

20 SEP 1929

2

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Stl Se MIRAMAR* Rpt. *B. As* No. *11001*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey

2nd S.S. No. 1


The *2nd S.S. No. 1* has now been held, and the following repairs done due to wear and tear:-

*vessel placed on slipway, bottom cleaned Coated.
Minor repairs effected.*

It is submitted the vessel is worthy to remain as classed, with record of Survey *8.29* and notation of *S.S. B.As M1-29* as recommended.

*100A.1.
8.29 B.As
S.S. B.As M1-29*

*J. 18.9.29
Wanna*



© 2020

Lloyd's Register Foundation

WS98-0150

It is concluded the machinery ~~work~~ space has been examined but the Surveyor should be requested to state if ~~this is so~~

*10.29
done. 10.29*