

2m, 10, 39.

at to Chief Surveyors

Received from Chief Surveyors **1 - JUN 1940**

VESSEL'S NAME

NATIA

Report

LIV

No. **114228**

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

ature of Survey

DOCKING

When due

*Subject to indented NOS 2+3 file sheer plates etc (5.5)
being repaired at the Owners' convenience*

*was
31.5.40*



© 2020

Lloyd's Register
Foundation

W 60-0123

Have the Tanks been examined internally? ☒

Air and Sounding Pipes ☒

Salting ☒

(State if examined.)

Have the Tanks been tested? ☒

Doubling Plates under Sounding Pipes ☒

Sails