



## Lloyd's Register of British &amp; Foreign Shipping,

3, Steinhoeft,

Hamburg, 30th November 1910

LLOYDS REGISTER,  
LONDON.  
REC'D 1 DEC 1910  
ANSPCommunications to  
be addressed to  
SURVEYORS.

Sir,

Reference  
M.

In reply to your inquiry of the 28th instant  
Respecting my First entry Report No 11741 on the steamer  
"ELMSHORN, I beg to advise you that the thicknesses of  
the Double keel plate Buttstraps, should be .68 and .64  
and that the Bulbangle frames in Forepeak should be 7x3 1/2  
x. 44 Please correct these slips on my Report.

I remain, Sir

Your obedient Servant

The Secretary

London,



© 2020

Lloyd's Register  
Foundation

DEC - 1 1910

Original filed at Lloyd's Register



DEC -1 1910

Yonr opeñent 2etant

ris, nismet I

Requesting my first year of service in the summer  
of 1971 on the basis of the fact that the thickness of  
the double wall plate butt joints shows a .08 in.  
and that the bulging in front of the wall is .2 x  
1.2 in. Please correct these slips on my Report.

The Secretary

полюс,

30-й ноябрь 1910

Foodwise, 3

212

© 2020

Lloyd's Register  
Foundation

by Chief

EL'S NA

The remar-

(“Th

5

# Journal of Survey

834.08 MOH 721 77

TELEPHONE: 393-9004 FAX: 393-9005  
STANLEY STEINHOFF HARDWARE