

LIST OF SPARE GEAR.

For Turbine:-

2 Bearings.
Spring for Turbine Quick Closing Valve.
Spring for Cut-Out Gear.
Spring for Turbine Blow-Off Valve.
Spring for Turbine Quick-Closing Governor.
14 Port and 14 Starbd. Michel Thrust Pads.

For Gearing :-

1 - 48 m.m. Coupling Bolt & Nut.
9 - 2 $\frac{3}{4}$ " Coupling Bolts & Nuts.
1 Coupling Bolt & Nut 105 m.m. long.
1 Coupling Bolt & Nut 110 m.m. long.
1 Ford. Bearing for Hydraulic Coupling Shaft.
1 Aft Bearing for Hydraulic Coupling Shaft.
1 Bearing for 1st. Reduction Shaft.
1 Ford. Bearing for 2nd. Reduction Shaft.
1 Aft. Bearing for 2nd. Reduction Shaft.
1 Bearing for Main Wheel Shaft.
18 port and 18 starbd. Michel 2nd. Reduction
Pinion Thrust Pads.
6 Port and 6 Starbd. Michel Main Thrust Block
Pads.

Fred. A. Hargreaves



© 2021

Lloyd's Register
Foundation

W61-0074