

2m.8.19.

1

Sent to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME STEEL S.S. "NARDANA"

Report Gls. No. 39167

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

Nature of Survey \_\_\_\_\_

When due \_\_\_\_\_

The Downston Pump has been dispensed with for the present, but it is included the Owners are agreeable to fit same when requested.


\* 100 A.1. (steel) "Shelter Dk. with Freeboard"

2 Dks (steel) and Shelter Dk. (steel)

Cell DB 386' 1460t. DTa 39' 1100t. FPT 125t. APT 80t

FK. BRH. 15 Shelter Dk. cent. Lloyd's A.C.P. P 31', 43', on Shelter Dk.

W61-0076



© 2019

Lloyd's Register  
Foundation  
M. A.S.  
9.10.19