

No. of Feed pumps 4 Diameter of ditto 4 1/2 Stroke 24 Can one be overhauled while the other is at work

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

10th October, 1919.

Dear Sir,

With reference to Glasgow Report No. 39167 on Machinery for the S.S. "NARDANA", I have to request that the Surveyors will be good enough to state whether they are correct in reporting the heating surface of the Boilers of this Vessel as 17352 square feet and NHP as 1150 in view of the heating surface of a Sister Vessel's Boilers being reported as 17079 square feet and the NHP as 1138.

I am, Dear Sir,

Yours faithfully,

Secretary.

The Secretary,

GLASGOW.



© 2019

Lloyd's Register Foundation

W61-0085

ratey Diameter Length Working pressure of shell by rules Diameter of flue Material of flue