



S/S "Serumoor"

IP guide shoe unmetalled, IP frame ring & bolts renewed  
IP balance piston rings renewed, HP piston rings & spring  
renewed, all holding down bolts tested.

Main Pumps thoroughly overhauled & a few repairs  
carried out. Main Condenser tested.

Electric wiring in Engine overhauled & made good  
and Installation tested & found in order.

A number of other minor repairs carried out.

All fittings removed for access replaced.

D.W.

REPAIR

REPAIR

