

N.B.—All alterations in the existing regulations must be made in the presence of the Surveyor. If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thickness of the floors, framing, and of the inner bottom plating, especially in the boiler spaces.

CHARACTER.  
\* for Spanish Survey.  
Date of last Survey and of  
Periodical Surveys.

Brms. 4.13.

LOYD'S REGISTER  
LONDON  
26 MAY 1914  
26

Time of Receipt

TELEGRAM.

POST OFFICE TELEGRAPHS.

If the Receiver of an Inland Telegram doubts its accuracy, he may have it repeated on payment of half the amount originally paid for its transmission. Any fraction of 10. has time 10. being reckoned as 10. and if it be found that there was any inaccuracy, the amount paid for repetition will be refunded. Special conditions are applicable to the repetition of Foreign Telegrams.

Handed in at	Office of Origin and Service Instructions	Words	Charges to pay	Office Stamp.
2/42	Middlesbro	(13)		RECEIVED MAY 26 1914 F. 10.17A

THIS FORM MUST ACCOMPANY ANY ENQUIRY RESPECTING THIS TELEGRAM. Received here at

TO { Committee Ldn

Moorish prince marks on  
Cable on Board agree with Certificate  
Surveyors



© 2020

Lloyd's Register  
Foundation

W619-0206




*Referred to the Chief Ship Surveyor.*

*C. A.*  
MAY 26 1914

*Also for Mr. B. de Hill to note:*

*M*  
*26-5-14*



© 2020

Lloyd's Register  
Foundation