

S.S. "YONAN MARU"

This vessel appears to have been carrying a deck load of timber, and if fully loaded the proportions of breadth to draught would indicate a reserve of stability below the average.

It is suggested it would be of interest to communicate with Mr. Cox, Principal Surveyor for Japan, with a view to his transmitting to this Office the result of any enquiry which may be held into the case of this vessel, and apart from that it would be interesting to have from him any information which he may be able to collect in regard to the draught and conditions of loading, including distribution of cargo, at the time she sailed.

Jul
21.10.31

ASL
Mr. Kob: 23.10.31



© 2021 73/10

Lloyd's Register
Foundation
W638-0034

$\frac{B}{D} = 1.6$