

3m.9.20.

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

MS 'OPAL'

Report

gls

No. *37573*

For the CHIEF SHIP SURVEYOR ~~or CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Damage

When due

Subject to stem & stemplating being repaired at Owners' Convenience.

The Certificate of Classification to be endorsed "*Cargo battens not fitted*" and the same notation to be printed in the Register Book.

MHB
20.5.31.



© 2021

Lloyd's Register
Foundation

W645-0006

this survey, thus, for example:—".....to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."