

AIRS, OR EXAMINATION AS PER RULE, FOR

Was a damage report made by anyone else? If so, by whom?

Condition

Chief Ship Surveyor

Received from Chief Ship Surveyor

16 MAY 1933

NAME Steel S.S. "JAMAICA PLANTER" Rpt. Lon. No. 98706

Acts of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32).

vey

The London Surveyors report this vessel placed in dry  
lock, bottom cleaned and coated.

It is submitted the vessel appears worthy to remain as  
classified with record of survey 4,33.

100 A. I.

Shelter D" with Hdd.

H. 33 Low.



© 2020 Lloyd's Register Foundation

his survey, thus, for example:—".....to remain as now classed in the Register Book without fresh record of survey," "to remain as classed and survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

This vessel is eligible in the opinion of the Surveyors to remain as now classed in the Register Book without fresh record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."