

1

Sent to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME Steel Sc. "ARGENTINE TRANSPORT" Report Gls. No. 56030**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey First Entry XXXXXXX --

\*100A1 with freeboard

1 Dk. &amp; Shelter Dk.

Cell. DB 351', 1082t, FPT 201t, APT 118t

FK, 6 EH (Coll. EH to Shelter Dk. 5 EH to 2nd Dk.) Cem. Lloyd's A &amp; CP.


F 35'

*[Handwritten signatures]*  
29.8.35.

The Surveyors should be requested to forward particulars of the length, including cofferdams and dry tanks (if tested), and capacity of the double bottom tanks, as these are not clear from their report.

*Lifts 29/8*

*See [unclear]*



Lloyd's Register  
Foundation

W66-0067