

after peak and after peak tanks examined. Tanks tested in accordance with
good and tight. Limber boards and ceiling lifted for this purpose and re-

S.S. "ELIZABETH"

{ Cr. Yr. 21930
{ Cr. No. 3609

It is submitted that
vessel is eligible for
RECORD.

L.M.C. 7.22 Subject to the Screw shaft
being specially examined at the joints of the liner
before the end of July 1924
"Fitted for Oil Fuel. 12.19." F.P. above 150°F.

7.22. C.L.

It is concluded that the Spare gear required by the
rules has been supplied, but the Surveyor should be asked
to confirm this. Yes. See N.Y.K. Ltr. 26/10/22.

C.A.R.B.

13/9/22

W660-0015

Ditto ditto at other places ditto

Reverse Frames

efficient?

Floors

Have Watertight Doors now been examined and found

Stringers Clamps & Shells

ditto

Keelsons

efficient?

Sailing

ditto

(State if examined.)