

F.E.

Ship Surveyor.....

Received from Chief Ship Surveyor.....

ME Steel S.S. "WESTERN VALLEYS" Rpt. Nwc. No. 72384

s of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

se No. 72 Depth "d" 21.7

Table No. 3 Description Bulb angle as approved.

dinal No. 23832

Proportions $\frac{\text{Length}}{\text{Depth}} = 10.03$

Deck Sheerstrake as approved.


The Downton pump has been dispensed with for the present and it is concluded the Owners are agreeable to supply same if requested to do so.

This vessel appears to have been built in accordance with the and the approved plans, and it is submitted she is eligible to ed 100 A.1. (Steel).

1.Dk. (Steel).

Cell DB 284' 714t. FPT 95t. APT 131t.

EK. 7BH. pt.Cem. Lloyd's A.& C.P. P33', B98', F29'.


23. 10. 19.



© 2021

Lloyd's Register
Foundation

W660-0252