

W663-0158

Chief Surveyors _____

Received from Chief Surveyors _____

 SHIP NAME Stl S M/V WINTON Report Srk No. 18968

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

 of Survey 1st Entry When due Revised Rules

✱ 100 A. I. (Steel). With keelboard

1 D^u (Stl) + Shelter D^u (Stl)

Cell D.B 319' 14425, M.T 28' 10505, F.P.T 1795, A.P.T. 2215
F.K, duct keel forward of machinery space.

7 B.H. (Coll B.H to Shelter D^u, 6 B.H to 2nd D^u) Lhyds A.C.P.
F 29'.

in fls 20/11/28

It is concluded the number of ~~painting~~ stringers and the thickness of the keel plates ~~at the ends~~ are as approved but the surveyors should be requested to state if this is so

© 2020

 Lloyd's Register
Foundation