

LIST OF SPARE GEAR SUPPLIED.

- 2 Bolts and nuts for H.P., I.P. and L.P. Rotor bearings. ✓
 2 " " " " Main gear wheel bearing. ✓
 2 " " " " pinion bearing. ✓
 21 Shaft coupling bolts. ✓
 $\frac{1}{20}$ of total no. of bolts or studs for gear case joint. ✓
 $\frac{1}{20}$ " " " " " " " " each turbine casing joint. ✓
 2 Thermometers for oil circulating system. ✓
 1 Set of bearing bushes for gear wheel spindle. ✓
 1 " " " " " H.P. and L.P. 1st reduction pinion shafts. ✓
 1 " " " " " " " " 2nd " " shafts. ✓
 $\frac{1}{2}$ Set of packing rings and springs for each turbine gland. ✓
 6 pads for main thrust block. ✓
 8 " " H.P. turbine thrusts. ✓
 8 " " L.P. " " ✓
 3 Liners for H.P. " " ✓
 3 " " L.P. " " ✓
 2 Propeller blades. ✓
 1 Escape valve spring for each size fitted. ✓
 100 Assorted Bolts, nuts and washers. ✓
 2 Springs for main Safety valves. ✓
 4 Valves and spindles for main and auxiliary feed checks. ✓
 12 Boiler tubes. ✓
 $\frac{1}{2}$ Set of firebars. ✓
 1 set of furnace front baffles. ✓
 1 firedoor. ✓
 1 Ashpit door. ✓
 12 Bridge segments. ✓
 6 Tube stoppers. ✓

