

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

12th May, 1920.

Dear Sir,

With reference to the Glasgow first entry report No. 39880 on the s.s. "EKARI" I have to say that it is concluded the rivets in butts of strake below sheerstrake are spaced 4 diameters apart as required.

It is also concluded that a set of liners for adjusting block, and one bucket and rod for lubricating oil pump have been placed on board, but as these items are not stated in the list of spare gear, I shall be glad if you will kindly ascertain from the Surveyors and let me hear from you on these points.

I am, Dear Sir,

Yours faithfully,

Secretary.

The Secretary,

GLASGOW.



© 2020

Lloyd's Register
Foundation

W68 2-0354