

1500,12,25.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor 20 JAN 1926

VESSEL'S NAME Stl. Sc. 4 Mst. Sr. "BEATTY ROSE". Rpt. Nyc. No 80030

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

Nature of Survey

The s.s. No.1 due 9-24 has been partly held.

The Newcastle Surveyors report the vessel placed in dry dock and damage through grounding and cause not stated repaired as follows:- 3 shell plates removed, faired and refitted, 3 faired in place, a number of rivets renewed in fore peak and minor repairs effected.


The s.s. No.1 has been completed and minor repairs carried out.

It is submitted the vessel appears worthy to remain as classed with record of survey 1-26 and notation of s.s. Bly. No.1-25.

100 A.1

1-26 Bly.

s.s. Bly. No.1-25.



© 2021

Lloyd's Register Foundation