

(3m,4,5.)

Received by Chief Ship Surveyor 13. 5-05

Received from Chief Ship Surveyor _____

VESSEL'S NAME 3. Met. Sch. William Morton Report Ind No. 2484

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey _____

First Entry

This Wood Schooner appears to have been built in accordance with the Rules and the approved sketch of midship section.

It is submitted she is eligible to be classed * 13A1, viz;

- 10 years Table A.
- 1 year Mixed Materials, Section 34.
- 1 year Metal fastenings, Section 46.
- 1 year Salting, Section 37.
- * 13A1 "10 & 12 yrs Mat", "cf", "Salted +",
"1 dk", "F&YM 3,05", "Lloyd's A&CP".

C. H. J.

13/5/05



© 2021

Lloyd's Register
Foundation

W 714 0063