

during a voyage from the Tyne to Rotterdam.

Jan. 11, 20.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

2 - JAN. 1922

VESSEL'S NAME Steel S.S. "PORTGWARRA".

Rpt.

Nwc.

No. 75062

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

The Newcastle Surveyors report this vessel examined afloat after encountering heavy weather.

The windlass has been renewed and 120 fathoms of cable of proper size, weight and test placed on board.

The vessel is stated to have been aground. This information was received after the completion of the Survey. The Superintendent, however, stated that all tanks and bilges had been sounded from time to time and the vessel found to be making no water.

The Surveyors recommend the vessel be placed in dry dock at the first convenient opportunity.

It is submitted action be deferred and the Owners informed of the Surveyors' recommendation.



© 2021

Lloyd's Register Foundation

2.1.22.

W 718 8025