

Do. of Houses on Dk. 2 0 2 2 2  
Do. of excess of Hatchways 3 6 - 1 0  
Do. above Crown of

stern post

Longitudinal Number

1 2 1 2 2 2

By whom built

For the information of Surveyors and the Committee only.

Received at

Office,

19

# Lloyd's Register of Shipping.

(Report on Vessel No. Port)

## 137. SHIP ~~FORGINGS~~ OR CASTINGS.

I have to report that the undermentioned ~~Iron or Steel Forgings or~~  
stings, manufactured by The Columbia Steel Company  
Pittsburg. Cal. for the Vessel No. 9. being built  
The Skinner & Eddy Cop. of Seattle Wash.  
ve been inspected by me as set forth below and found to be, so far as can  
seen, Sound.

Stern frame in two sections.

R. B. Batchelor.

San Francisco

oyd's

137.

6/17

	STERN FRAME.	RUDDER FRAME.	STEM.
...	<u>Of Steel.</u>		
...	<u>Cast.</u>		
...	<u>As per plan.</u>		
...	<u>Cast.</u>		
Inspection ...	<u>June 4<sup>th</sup> &amp; 11<sup>th</sup> 1917</u>		
Inspected			
TINGS.			
Standard Test			
pieces.			
t—			
quare inch	<u>64000.</u>	<u>64500.</u>	
per cent. ...	<u>31</u>	<u>29</u>	
ng Test—			
re fracture	<u>120.</u>	<u>120.</u>	
m ground ...	<u>Seven feet</u>	<u>Seven feet</u>	
Test—			
ording to Rules	<u>Yes.</u>	<u>Yes.</u>	
id satisfactory ...			

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

if any chargeable) ± \$20.00.  
Expense in San Francisco



© 2021

Lloyd's Register  
Foundation

220 & 219

W 718-0147

W 718-0146