

2m,11,20.

24 JAN 1922 1

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

Shells Larinside

Rpt.

Sh

No. 28247

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

Nature of Survey

DAMAGE.

Damage through

Collisions &c

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str.	Plates	Dk.	Plates
Renewed	7				3	2		1	
Removed and faired or repaired.....	12	10			9	1			
Faired or repaired in place.....	6	6			1	1		2	

Other items:-

*Vessel placed in ship, bottom & under clean & coated,
Casings, bulwarks, big keels, quadrants &c repaired as required
& minor repairs carried out.*

It is submitted the vessel is worthy to remain as classed with

record of Survey 1.22 as recommended

100A.1.

1.22



© 2021

Lloyd's Register
Foundation

W737-0068

Travelling Expenses (if chargeable)

Surveyor to Lloyd's Register