

Im. 12.15.

F.E.

Received by Chief Ship Surveyor

15.10.17

Received from Chief Ship Surveyor

VESSEL'S NAME

Sheels Wyndhurst

Rpt.

Abn

No. 11979

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

40.08

Depth "d"

10.73

Framing: Table No.

3 page 9

Description

Single Angle as appraised

Longitudinal No.

6596

Proportions

Length

12.46

Depth

~~Deck~~ Sheerstrake

as appraised.

Cargo battens are not fitted.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ✱ 100 A.1 (Steel) as recommended.

1.DK. (Steel) Well Deck

Cell D.B. 72' = 118L. F.P.T. 44L.

FK. 3BH. Cam. Lhyd. and CP. Q 94' B11' F23

Manch. appd.

M

The Certificate of Classification, to be endorsed "Cargo battens not fitted," and the same notation to be printed in the Register Book.



© 2020

Lloyd's Register  
Foundation

Deck. Material and thickness

Bridge Deck Stringer Plate, br'dth &amp; thickness