

by Chief Ship Surveyor 29.6.14

Received from Chief Ship Surveyor 3 JUL 1914

EL'S NAME Steel 1/2" Sharon Rpt. Sld No. 26155

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Remarks of Survey Condition

The class of this vessel is subject to the saloon skylight and companion door being permanently repaired at the Owners' convenience.

The Sunderland Surveyors now report that this vessel has been examined in drydock, the bottom has been cleaned and coated and some minor alterations effected.

It is submitted the vessel appears worthy to remain as classed with record of survey 6.14, subject, as above.

100A1 } Subject
6.14 Sld } etc.

M W.H.M.
2.7.14.

N.B. The Surveyors should be requested to state whether the repairs referred to in the Special Reasons List have been carried out at this time.



© 2020

Lloyd's Register
Foundation