

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

24th January, 1927.

Dear Sir,

S. With reference to Greenock First Entry Report No. 18643 on the Steamer "RODNEYSTAR", I have to say it is concluded that the thickness of the bridge deck plating abreast the openings is .56, but I shall be glad if you will kindly ascertain from the Surveyors and let me know whether this is so.

I am, Dear Sir,

Yours faithfully,

Clerk to the  
Classification Committee.

The Secretary,

GLASGOW.



© 2020

Lloyd's Register  
Foundation

W77-0145