

W77-0146

Chief Surveyors

Received from Chief Surveyors

EL'S NAME Stl T.S. "RODNEY STAR" Report Snk No. 18643

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.5.92.)

of Survey 1st Entry When due Revised Rules

✠ 100 A.I. (Steel) "With freeboard"
 3 Dks (Stl). 4" Dk (Stl) in No 1. 2. 3. 5 & 6 holds } subject to indented
 Cell D.B. 404' 1419t, F.P.T. 103t, A.P.T. 116t. } plating being dealt with
 at the owners convenience
 F.K, Duct Keel forward of machinery space 140', 8 B.H, pt cem, Lloyds A.C.P.
 P 72', B 200', F 39'.

It is concluded the thickness of the Bridge deck plating abreast the
 11/17 openings is .56, but the Surveyor should be requested to state if this is so.

Lt 24/11/27

2020 12.1.27

Lloyd's Register Foundation