

10m.11.20.

Wreck 46

12 JUN 1921

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Steel Sp. "IMPOCO". Rpt. Hfx. No. 1357

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

The Halifax Surveyor report this vessel to have been examined in dry dock after having sustained extensive damage through stranding.

Recommendations have been made for permanent repairs but the vessel has been removed from the dry dock and beached and it has not yet been decided whether repairs will be effected or whether the vessel will be considered as a constructive total loss.

In the Surveyor's opinion the vessel is not now in a fit condition, or eligible, to remain as classed.

It is submitted the class of the vessel be expunged from the Register Book and "Stranded - In port damaged, 5.21" inserted.

  
8. 7. 21.

© 2020

Lloyd's Register  
Foundation  
W483-0050