

WB=Cell D Boy D Ba
total capacity tons. FPT tons; APT tons; MT feet tons.

precisely as in Reg

CHARACTER.

vey,
and of
eys.

Subject to slightly indented poop sheerstrake and deck
plating (P.S.) being dealt with at the first convenient opportunity

11

8 - JUL 1940

Chief Ship Surveyor

Received from Chief Ship Surveyor

S NAME SANTA MARGARITA Rpt. BRY No. 24331

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)


Survey DOCKING

The *Bary* Surveyors report this vessel placed in
dry dock, bottom cleaned and coated, ~~repairs or renewals to~~
and minor repairs effected.

Nothing done to indented plating, as above.

It is submitted the vessel appears worthy to remain as
classed with record of survey 6-40 as recommended *subject as above*

100 A-1.
6-40 BRY } *Subject etc.*



© 2020

Lloyd's Register
Foundation

W79-0002

Outside lashing

0✓

(State which.)

Rudder

good

Hatches

Condition

(State)