


It is submitted the Surveyor be informed that the Society's plans sent to him for his information and guidance should not have been allowed by him to go out of his own possession. The First Entry Report should be returned to this Office, and he should be careful to see that the plans lent by him to the Repairers are returned to him as early as possible. These should be sent back to this Office in due course.

23.10.20

© 2021

Lloyd's Register
Foundation

W796-0011



Spel