

1 2m. 8.19.

W 45 (Bottom)

W796-0093

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME STEEL 2 1/2" TREVALL

Report Gls.

No. 39118.

For the CHIEF SHIP SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

The Downston Pump has been dispensed with for the present, but it is concluded the Owners are agreeable to fit same when required to do so.

\* 100 A.1. (steel)


1 Dk. (steel)

Cell DB 342' 1059t. FPT 127t. APT 218t.

FK. 7BH. pt. cem. Lloyds A & C.P. P49' B 113' F 88'

The Certificate of Classification, to be endorsed "Cargo battens not fitted," and the same notation to be printed in the Register Book.

It is concluded Relieving Tackles are fitted in lieu of Hand Stunners Gear but the Surveyor should be requested to check if the second "pot cem" should be made in this case



(e) .....  
dgy