

Engine Room ...
TONNAGE FOR FEES..

Long Bridge Deck

1690.49

Proportions—Depths to Length—Upper Deck Beam at side to top of keel

12.9

Residence

Long Bridge Deck

10.27

Port belonging to

1680-0170

1

Queen Alex

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

Steel S.S. "WAR ANCHUSA".

Report

Grk.

No.17407

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/03.)

Nature of Survey

When due

The Downton pump has been dispensed with for the present as approved in Standard Vessels.

* 100 A.1. (Steel).

1 Dk. (Steel).

Cell DB 340' 1051t. FPT 128t. APT 220t.

FK. 7 BH. pt.Cem. Lloyd's A. & C.P. P50', B113', F39',

The Certificate of Classification, to be endorsed "Class not fitted," and the same

CENTRE GIRDEL

in db. bottom, open & thickness

Angles, Top

Attached to outside plating with Angle.....