

Are the cylinders fitted with safety valves

Are the exhaust pipes and silencers water cooled or lagged with non-conducting material

(Received at London Office.....19....)

No. 20. Place Dursley, Gloucester, Date 23. Sept. 1936.

We request that the Committee of Lloyd's Register will instruct the Society's Surveyors to survey and inspect the following Auxiliary Sets to the order of Vickers-Armstrong, Barrow-in-Furness - Order No. 16779 E/SUB of 27. Aug. 1936 - Our Works Order No. 17,746 = consisting of:- Set "A" One 38 1/4 HP. Light Diesel Eng. c/wd. Retro V. Dynamo 15 Kw. c/wd. Air Compressor. Set "B" One 38 1/4 HP. Light Diesel Eng. c/wd. Dynamo a set A c/wd. Centrifugal Bilge pump.

We undertake to arrange for every facility to be given to the Surveyors to carry out the duty in question, and we agree to pay the fees for the Surveyors' services, in addition to the actual travelling and other expenses incurred by the Surveyors in connexion therewith.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that:-

While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society.

pp. R.A. Lister (Hamm Sales) Ltd

To the Secretary,

Lloyd's Register of Shipping,

71, Fenchurch Street, London, E.C.3.

Lloyd's Register
Foundation

W81-0093