

W834-0047

2nd, 7, 16

1

Chief = 4 B

Sent to Chief Surveyors 8.11.16

Received from Chief Surveyors

VESSEL'S NAME

Shess Limesfield

Report

his

No. 75674

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

✱ 100 A-1. (Steel)

1 DR (Steel) Weld DR

D.T. + 16' 33L. Q.P.T. 6L

BK 6 1/2 4BH. cam. Leads arep. Q 85 139' F 23' *Med. cable*



© 2020

Lloyds Register Foundation

8.11.16

thickness of Middle Line Strake

Third-Deck Stringer Plate, br'dth & thickness

Angles on ditto No.