

W/EP.

ALL REPLIES TO BE ADDRESSED
SUPT'S.
TO..... DEPT.

FRIDAY, 6th Aug. 1915.

Mrs Ropner & Sons, Ltd.,

Stockton-on-Tees.

Sirs,

"No. 503 s/s SROCKLESS ANCHORS."

We are in receipt of your letter of yesterday's date and note that the aggregate weight of the Anchors is $\frac{3}{4}$ cwt less than that of what they should be according to Lloyd's rule, and that we give you our consent to this arrangement. Owing to the unprecedented pressure for Admiralty and other work we will agree to the same.

Yours faithfully,

FOR CONSTANTINE & PICKERING STEAMSHIP CO.

W Constantine

REGISTERED
1915
COGN



© 2020

Lloyd's Register
Foundation

W835-0022

angles on upper edge
spacing
top Deck, Angle, Bulb Angle, Plate,)

6	3	4	6	3	4
---	---	---	---	---	---

Bridge Deck Stringer Plate, br'dth & th

When built 1915
ham built
inter
ridg
ppe
spa
RS.
atab
stal P
Sh
Thru
leng
l
ith Ang
l
ith Ang
leng
ith Angl
th & thick
ar of Bri
th & thick
ay of Bri
r of Bridg
Hatchway
Full
Bridge)
of Bridge)
ckness
r'dth & thi
ways
hickness
, br'dth & thi
chways.....
ickness
Stringer P
breadth & thic
ditto, No.
outside Hat
ickness
, breadth & th
ickness