

W839-0089

3

Inspected by Chief Ship Surveyor 1. 4 15 Received from Chief Ship Surveyor _____

VESSEL'S NAME Steel SS Marieu Rpt. Inv No. 67345

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey S.S. No. 2 AND DAMAGE.

Damage through Grounding

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed	7						
Removed and faired or repaired.....	3	1 pl-					
Faired or repaired in place.....	9	13					

Other items:-

Vessel examined in dry dock, bottom cleaned & contact & minor repairs carried out

The ^{Completed} S.S. No. 2 has also been held and following repairs done due to wear and tear:- Hatch coamings, prescripts re repaired as required & minor repairs carried out

It is submitted the vessel is worthy to remain classed with record of Survey 3. 15 and notation of A.S. Dem No 2-14 as recommended.

100A-1.
3. 15 shd
AS Dem No 2-14

The Dundee Surveyors should be informed (with reference to their report No 7842) it is concluded the ceiling was tested & required by the Rules & registered to state if this is so

