

F.E.

Received by Chief Ship Surveyor 16-10-13

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME M.S.S. Mercionethshire Rpt. Sld No. 25876

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 79.41 Depth "d" 24.41  
Framing: Table No. 3 page 16 Description Bulk angle as approved.  
Longitudinal No. 30572  
Proportions  $\frac{\text{Length}}{\text{Depth}} = \frac{10.7}{1}$   
*Shelter* Deck Sheerstrake as per Rule


This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed + 100 A.1 (Steel) "Shelter deck" with freeboard," as recommended. The Summer freeboard of 3.4½ from centre of disc to top of statutory deck line at Upper deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

+ 100 A.1 (Steel) "Shelter deck with freeboard"

1 SH (SH) & Shelter SH (SH)

M.B. Cell SHa 133'w E 23' f 168' 9086. J.P.J 1306 AR 1046

J.H. 6 RH. Csm Layers a & C.P.



© 2021

Lloyd's Register

Foundation

P.T.O