

P. TAYLOR,  
MARINE SURVEYOR,  
FOR LLOYD'S REGISTER  
S. & F. S.

TELEGRAPHIC ADDRESS:  
"RION" RANGOON.

Rangoon, 2nd. January 1920.

LLOYD'S REGISTER,  
LONDON.

RECD 28 JAN 1920

Andrew Scott, Esqr., ANSD

Secretary to Lloyds Registry

L O N D O N.

Dear Sir,

I beg to acknowledge receipt of your letter M dated the 27th November last with reference to the wood sailing vessel "Hyastan" and to my First Entry Report No.319 which I very much regret contains several mistakes.

As requested I herewith furnish you with fresh particulars of the vessel as she was built and also enclose a corrected First Entry Report and plan of Midship section, which I trust you will now find in order.

Siding and moulding of floors	14 $\frac{3}{4}$	. 14 $\frac{3}{4}$
" - " - 1st foothooks	14 $\frac{3}{4}$	. 13 $\frac{1}{2}$
" - " - 2nd " -	14 $\frac{3}{4}$	. 12 $\frac{1}{2}$
" - " - 3rd " -	14 $\frac{3}{4}$	. 10 $\frac{1}{4}$
" - " - toptimbers	14 $\frac{3}{4}$	. 7 $\frac{1}{2}$

Size of 2nd deck beams:- 15 x 15 and 15 x 13 at ends.

Width and thickness of upper deck planking:- 6" x 3 $\frac{1}{4}$ "

Size and number of bilge logs:- 12"x 12" three each side.

Diameter of bolts in deck shelves:- 1 $\frac{1}{4}$ "

Number of planks between butts on same timber:- not less than three.

Length of Stream chain 75 fathoms.

Pumps:- good and efficient.



© 2020

Lloyd's Register  
Foundation

W860-00772



Ceiling edge fastened with  $\frac{5}{8}$ " spikes.

Wales edge fastened with  $\frac{1}{4}$ " bolts.

No diagonal iron plates were fitted as per section 39.

I am, Dear Sir,

Yours faithfully,

*R. P. Bayley*

Surveyor to Lloyds Register.



© 2020

Lloyd's Register  
Foundation  
W860-0077 2



Referred to the Chief Ship Surveyor.

7A M.

28 JAN 1920

Also for Mr. S. A. Bell to note.

Shanks & Co. Ltd.



© 2020

Lloyd's Register  
Foundation