

Chief Ship Surveyor 12.7.17

Received from Chief Ship Surveyor 13 JUL 1917

NAME Steel s. s. Helston Rpt. Sws No. 14297

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/6/02.)

DAMAGE.

Survey

The class of this vessel is subject to some collision damage being repaired. (See Ssw Rpt. 9726)

Damage through collision & causes unknown.

Repairs as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed	12	1			1		3
Moved and faired or repaired		3					
Faired or repaired in place	2						

Other items:-

Vessel examined in dry dock.
Bottom cleaned and coated.
Minor repairs effected

The Surveyor recommends some further repairs be completed at the first favourable opportunity.

It is stated the vessel has now been sunk.

It is submitted the vessel is worthy to remain as classed with

record of Survey 6.17 as recommended subject etc & without etc.

100 A.1.
6.17 Sws

} without etc
Subject etc



© 2021

Lloyd's Register
Foundation
13.7.17

W872-0131