

18 1806, A.B.C. 5TH ED. & WATKINS.
RUE 3712-3713.
LAND: "WINDLASS, LED, LONDON."
REIGN: "WINDLASS, LONDON."

LLOYD'S REGISTER
LONDON.

LLOYD ROYAL BELGE (GREAT BRITAIN) LTD.

101, LEADENHALL STREET
LONDON, E.C. 3.

REC'D JAN 30 1918

ANSD

1/2/18

LONDON, Jan. 29. 1918 19

A. F. BRYE, Chairman H. M. GYLSEN, Managing Director
ARM. GRISAR, Director
ALB. KREGLINGER, Director
(All Belgian Nationality).

The Secretary,
Lloyd's Register of Shipping
71 Fenchurch Street. E.C. 3

Dear Sir,

S.S. "GALLIER".


When this vessel was at Havre last month, she entered into collision with the Trawler Mines, and as the "GALLIER" has, unfortunately, since then been sunk, we wish to have from your Surveyor, who examined the damage at Havre, an estimate as to the cost of repairing same damage.

We beg herewith to enclose a copy of the letter we have received from Mr. H.P. Read, your Surveyor at Havre, and shall be greatly obliged if you will kindly instruct him to let us have what we require, viz. - this estimated cost for repairs to damage, as above, as noted in his report, dated December 28th. 1917.

Thanking you in anticipation,
We beg to remain,

Yours faithfully,

LLOYD ROYAL BELGE (Great Britain) LTD.



Superintendent.

Copy of letter enclosed.



© 2020

Lloyd's Register
W896-0041
Foundation

Referred to the Chief ~~of~~ Surveyor,
and the Chief Engineer Surveyor.

C.A.

JAN 30 1918

Also for Mr. S. A. Hill to note.

Referred to Mr. Munn

J.M.

1/2/18

subsequent to

San Jose 1911 to 1912

1918

San Jose 1911 to 1912



© 2020
Lloyd's Register
Foundation

Messrs
Sirs,
enclos
conten
Dec. 1
with t
win, w
togeth
the He
approa
carry
pairs
1 enc