

24 OCT 1917

3

Chief Ship Surveyor 24-10-17

Received from Chief Ship Surveyor

NAME Steel S.S. "Fritjof Rinde"

Rpt. Bgn. No. 1219.

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

Survey 1st S.S. No. 3 AND DAMAGE

Damage through grounding.

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed	-	-		-			
Removed and faired or repaired.....	30	21		14			
Faired or repaired in place.....	20	15		19			

Other items:- Vessel examined in dry dock, bottoms cleaned & coated, centre longitudinal, tank margin plating & intercostals and bulwarks renewed or repaired as necessary. Minor repairs effected.

The 1st S.S. No. 3 has also been held and following repairs done

due to wear and tear:- Deck & tank top plating and hold pillars renewed or repaired as necessary. Minor repairs effected.

It was not considered necessary to drill the shell plating.

The Surveyor was authorized to hold this survey.

It is submitted the vessel is worthy to remain classed with record

of Survey 10-17 and notation of S.S. BGN. N° 3-10-17

is recommended.

100 A.1.

S.S. BGN. N° 3-10-17

10-17 BGN.



© 2020

Lloyd's Register Foundation

W902-0241