

Do. of
Do. of
Do. of
Do. of
Enain

1m, 12, 15.

F.E.

Received by Chief Ship Surveyor 25.5.16

Received from Chief Ship Surveyor

VESSEL'S NAME Sheels Thimston

Rpt. Hub No. 9339

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 83.78

Depth "d" 24.96

Framing: Table No. 3 page 16.

Description Bulb angle as approved.

Longitudinal No. 34768

Proportions Length 11.4
Depth

Bridge Deck Sheerstrake as approved.

RETAIN

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed * 100A.1. (Steel) as recommended.

* 100A.1. (Steel)

1 Dr (pt in pt ste)

See DB 364' 17236. F.P.T. 1546. A.P.T. 1836.

FK. 7BH. See Logbook. P45 B+F 321.



© 2020

Lloyd's Register
Foundation