

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 19-2-41 When handed in at Local Office 19-2-41 Port of Swansea

No. in Reg. Book 85156 Survey held at Swansea Date, First Survey Feb. 4. Last Survey Feb. 4. 1941. (No. of Visits One)

on the Wood-Iron or Steel TRELAWNY

TONNAGE:-
GROSS 4689.
UNDER DK. 4379
NET 2818.
Built at Newcastle By whom Hawthorn Leslie & Co Ltd When 1927 9.
Owners Bain & Co Ltd Owners' Address (if not already recorded in Appendix to Register Book).
Managers Port belonging to London.

Surveyed Afloat or in Dry Dock? Name of Dock Kings. Destined Voyage
Cell DB or DBa feet; uE&B feet; f feet }
total capacity tons. FPT tons; APT tons; MT feet tons. }
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

N.B.—All alterations in the existing records should be underlined.
Last Report, No. 3536 Port Bos

CHARACTER: * for Special Survey, Date of last Survey and of Periodical Surveys.
Machinery and Boiler Surveys (including date of N.B., if any).
+ 100 A1.
SS Bff. No. 2-37.
Examined 10-40.
A.S. Bff. No. 2-37
+ LMC 4.36 MS 7-40.
BS 10-40.
CL. 6-40.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined
shelter deck with freeboard
Society's Freeboard (if assigned) as painted on Ship and now verified

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Repairs.

Found Small fracture in 2nd plate from stem starboard side in 5th strake below steel

Done Fracture & two rivets electric welded, 4 rivets caulked.

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Caulking of Decks	Cement or Asphalt	Oil Bunkers	Boats
Coamings	Rudder	Scuppers	Masts, Yards, &c.
Rivets & Fastenings	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed)
Outside Plating	Windlass	Hatches	Equipment letter
" " in way of sidelights	Have pumps been examined and found efficient?	Planking	Anchors, No. of
Frames	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
Reverse Frames	Have Watertight Doors been examined and found efficient?	Treenails	" length mean diamr. (on board)
Longitudinals	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stems	" Rule length size
Transverses	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
Floors	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
Keelsons		" " at other places	Standing and Running Rigging
Stringers		Stringers, Clamps & Shelves	Sails
Inner Bottom Plating		Salting (State if examined.)	
Have the Tanks been examined internally?			
Have the Tanks been tested?			

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

This vessel in my opinion is eligible to remain as classed without fresh record of survey.

Survey Fee (per Section 29) £	Fees applied for, £
Special Damage or Repair Fee (if any) (per Sec. 29) £	19
Travelling Expenses (if chargeable) £	Received by me, £
Second Surveyor's Fee (if any) £	19

Committee's Minute
Character Assigned Refused
TUE. 4 MAR 1941
J. Thompson
Surveyor to Lloyd's Register of Shipping.



W92-0025