

3m,11,39.

6 - JUN 1940

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME "W. B. WALKER" Rpt. Lon No. 108713

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to shell plates D.2 & E.2, starboard side, being dealt with at the first favourable opportunity.

Sta 3941
- 139

The 1st Special Survey No. 1 has been held on the hull.

The London Surveyors now report the vessel placed in dry dock, the bottom coated, and minor repairs carried out.

Shell plates D.2 & E.2 (s.s.), as above, continue efficient.

It is submitted the vessel appears worthy to remain as classed with record of survey 5.40, subject as above.

100A1)
5.40 Lon) Subject, etc.
Carrying petroleum in bulk)



© 2020
Lloyd's Register
Foundation
3.6.40
W93-0029

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book this survey, thus, for example:—".....to remain as classed in the Register Book without fresh record of Survey," "to remain as classed as