

4m,8,15.

CHECK 12 ✓
Mack Box No. W-12 I

3 JAN 1916

Received by Chief Ship Surveyor 31. 1. 16

Received from Chief Ship Surveyor

VESSEL'S NAME Stl. S.S. "DEVIAN".

Rpt. Off.

No. 38385

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Common

This vessel has been placed in dry dock, the bottom cleaned and coated.

The Starboard Hawse Pipe which was fractured whilst stowing the Anchor has now been renewed, and minor repairs effected.

It is submitted the vessel appears worthy to remain as classed, with fresh record of survey as recommended.

100 A. 1.

1-16 Eff. M

[Signature]

31. 1. 16



© 2020

Lloyd's Register Foundation

W946-0006

Committee's M...
th...
su...