

2m.7.16.

Wreck 11

WRECK BOX  
No. 11. Bottom

23 AUG 1916

Received by Chief Ship Surveyor 22. 8. 16

Received from Chief Ship Surveyor

VESSEL'S NAME Stl. Sr. "DARTMEET". Rpt. Cff. No. 38945

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Condition

The Cardiff Surveyors now report this vessel has been examined in dry dock, and the bottom cleaned and coated.

weld at the  
The lower part of the rudder post was found to be open and has been repaired by fitting efficient clamp plates.

It is submitted the vessel appears worthy to remain as classed, with record of survey 8. 16, as recommended.

100 A.I.

8. 16 Cff

23. 8. 16

Lloyd's Register  
Foundation

Revers  
Floors  
Keel