


of "Beaufront."

Nwc. Rpt. 67705.

It is submitted that the Newcastle Surveyors should be asked to state whether they are correct in reporting the screw shaft as being fitted with a continuous liner, whereas the size they give as per Rule 12.65" is that required for a shaft fitted <sup>with</sup> two liners.



© 2021  
JTC

Lloyd's Register  
Foundation